

03500.017404



PATENT

CofC\$

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	Examiner: Tai Nguyen
	:	
AKIHIRO MOURI ET AL.)	Group Art Unit: 3729
	:	
Application No.: 10/618,676)	U.S. Patent No.: 6,993,840 B2
	:	
Filed: July 15, 2003)	Issued: February 7, 2006
	:	
For: MANUFACTURING METHOD OF)	June 21, 2006
LIQUID JET HEAD	:	

Commissioner for Patents
P.O. Box 1450
Alexandria, Virginia 22313-1450

ATTENTION: CERTIFICATES OF CORRECTION BRANCH

**CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323**

**Certificate
JUN 26 2006
of Correction**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050), in duplicate, is enclosed.

06/22/2006 CCHAU1 00000151 6993840

01 FC:1811

100.00 OP

2006

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Attorney for Patentees
Douglas W. Pinsky
Registration No. 46,994

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200
DWP/lip
DC_MAIN 244471v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,840 B2

DATED : February 7, 2006

INVENTOR(S) : Akihiro Mouri et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 21, "these" should read --over the last--.

COLUMN 7

Line 65, "are formed" (second occurrence) should be deleted.

Line 66, "soluble" should read --solution--.

COLUMN 8

Line 37, "this-manner," should read --this manner--.

COLUMN 10

Line 8, "5 parts was" should read --5 parts||was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,993,840 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/lip DC_MAIN 244471v1



2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,840 B2

DATED : February 7, 2006

INVENTOR(S) : Akihiro Mouri et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 21, "5 parts was" should read --5 parts¶was--.

Line 60, "5 parts was" should read --5 parts¶was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,993,840 B2

No. of add'l. copies
@ 30¢ per page

4006



Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/llp DC_MAIN 244471v1

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,840 B2

DATED : February 7, 2006

INVENTOR(S) : Akihiro Mouri et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 21, "these" should read --over the last--.

COLUMN 7

Line 65, "are formed" (second occurrence) should be deleted.

Line 66, "soluble" should read --solution--.

COLUMN 8

Line 37, "this-manner," should read --this manner--.

COLUMN 10

Line 8, "5 parts was" should read --5 parts¶was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,993,840 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/llp DC_MAIN 244471v1



JUN 26 2006

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,993,840 B2

DATED : February 7, 2006

INVENTOR(S) : Akihiro Mouri et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 11

Line 21, "5 parts was" should read --5 parts¶was--.

Line 60, "5 parts was" should read --5 parts¶was--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,993,840 B2

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30) DWP/ljp DC_MAIN 244471v1



2006